

An In-Depth Budget Review of the Utah Department of Transportation




Report to the Legislative Audit Subcommittee

September 2016

Audit Scope and Objectives



Chapter II



Improved Budgetary Controls Are Needed

Budgeting for Equipment Management Is Not in Line with Statute

Longstanding Use of Dedicated Credits is Not Consistent with Statute

Double-Counts Revenues
Dedicated Credits

Appropriations

Equipment
Management
Line Item

Equipment

Rents and Usage Fees

Operations and Maintenance Line Item

Inappropriately Transfers Money Between Line Items

FOR MORE INFORMATION

See Chapter II, pages 12-14

Budgeting and Accounting for Cooperative Agreements Needs Improvement

Local Projects Inflate UDOT Expenditures

Underestimated in UDOT's Budget

Inapropriately Labeled as Dedicated Credits

Recommend a Separate Line Item for Cooperative Agreements

FOR MORE INFORMATION

See Chapter II, pages 15-18

UDOT Oversight of B&C Road Funds Needs Improvement


B&C Road funds statute should be updated to reflect current practice.

UDOT does not verify compliance for the use of more than \$126 million in B&C road funds


FOR MORE INFORMATION

See Chapter II, pages 18-19

Transportation Investment Fund Obligations Reduce Funds for Capacity Programs



Transportation Investment Fund Obligations Reduce Funds for Capacity Programs




— Estimated Maintenance Costs Linear (Estimated Maintenance Costs)

FOR MORE INFORMATION


See Chapter II, pages 21-22

Chapter III



Outsourcing Needs to Be Evaluated by UDOT

UDOT is Filling Some Vacant Positions With Consultants



Consultants Cost Significantly More Than Comparable In-House FTEs


	Total Hourly Cost	
Position	Outsourced	In-house
Right of Way Agent I	\$101.29	\$39.87
Purchasing Agent II	\$103.00	\$32.86
Engineering Manager II	\$183.00	\$68.97

FOR MORE INFORMATION

See Chapter III, pages 29-31

Some Maintenance Activity Costs Are Higher Because of Outsourced Work






FOR MORE INFORMATION

See Chapter III, pages 35-40


Chapter IV



Contract Oversight Needs to Be Strengthened

109 Signs Installed Incorrectly on SR 36






FOR MORE INFORMATION

See Chapter IV, pages 43-44


Signs with Safety Concerns on Bangerter



FOR MORE INFORMATION

See Chapter IV, page 45

Signs with Safety Concerns on Bangerter



FOR MORE INFORMATION

See Chapter IV, pages 45-47

Chapter V



Enhanced Cooperation and Oversight Would Strengthen the Corridor Preservation Fund

More Proactive Measures Could Strengthen Corridor Preservation Fund

Actions by some municipalities cost the CPF millions


Some municipalities work well with UDOT to efficiently use CPF monies

We recommend that UDOT be more proactive in working with municipalities

FOR MORE INFORMATION

See Chapter V, pages 49-54

An In-Depth Budget Review of the Utah Department of Transportation



Report to the Legislative Audit Subcommittee

September 2016